

STATEMENT ACCOMPANYING FORM 'A'

1. Door Number of the building : **Sakthi Vinayagar Hindu Vidyalaya School**
2. Location (Street No. Ward No.,
Name of place, (i.e. Corporation /
Municipality), Panchayat /Panchayat
Union / Township / Contonment : S. No- 494/4A, Door No- 23,
Chidambara Nagar, Tuticorin
Municipality
3. Year of Construction : 1983 & 2003
4. Approximate cost of construction
as per current rates : Rs. 20,00,000/-
5. Purpose for which the building is
being used or proposed to be used : **For accommodating School class rooms**
6. Purpose for which the building has
hitherto been used : **For accommodating School class rooms**
7. Details of construction of the
building (Particulars of the
foundation, soil, specification of the
various part under)
 - (1) Foundation : R.R masonry in CM
 - (2) Basement : R.R masonry in Cm
 - (3) Superstructure : Brick work in Cm
 - (4) Floor and roof are to be given : Ground floor and First floor RCC roofing
Cement flooring, partly RCC and partly AC
sheet roofing and Cement flooring in SF
8. Period for which license is required : 19.2.2022 to 18.2.2025
9. Number of persons to be accommodated: 1000 (One Thousand)

CERTIFICATE PRESCRIBED

"Certified that no addition or alteration has been made to the existing building or portion of the building for which this application has been made, I undertake to obtain a fresh license in case any addition or alteration is made to the existing building or portion of building. I also undertake to obtain a fresh license if the purpose for which the license was granted for the use of the building or portion of the building originally is changed or altered subsequently"

Signature of the owner of the Building

Signature of the Dist. Panel Engineer (class – IA)

Date : 24.02.2022

Place : Tuticorin




PRINCIPAL

**SAKTHI VINAYAKAR HINDU VIDYALAYA
CBSE SENIOR SEC.SCHOOL, TUTICORIN**



SECRETARY

**SAKTHI VINAYAKAR HINDU VIDYALAYA
TUTICORIN**


T. MURUGESAN, BE, MIE, FIV.
DISTRICT PANEL ENGINEER
TUTICORIN
42, ...
Phone ...

FORM B

Form of certificate of structural soundness under sub-section (4) of section 4 of the Tamil Nadu Public Buildings (Licensing) Act, 1965 Tamil Nadu Act 13 of 1965 referred to in rule 4 of Tamil Nadu Public Buildings (Licensing) Rules, 1966 and G.O.M.S.No.393 School Education Department dated 11-09-1997.

**Sakthi Vinayagar Hindu Vidyalaya School, S. No- 494/4A, Door No- 23,
Chidambara Nagar, Tuticorin, Tuticorin taluk & district**

I certify that I have inspected the buildings mentioned in the statement and furnish below its salient technical features :-

1. Foundation
 - i. Depth below ground level ... **1.10 M**
 - ii. Nature of soil met with at foundation level ... **Sandy soil**
 - iii. Pressure at foundation ... **11.05 t / m²**
 - iv. Probable safe bearing capacity of the strata met with at foundation ... **25 t / m²**
2. Superstructure
 - i. Maximum stress in the most critical section of masonry and concrete ... **37.09 t / m²**
 - ii. Nature of masonry and its safe permissible stress ... **Brick work in cement mortar
68 t / m²**

The structural soundness of the building has been verified by me with reference to Indian Standard Institute loading standards 875 (latest version) and other relevant Indian Standard code of Practice and I declare that the building is structurally Sound to be used as a public building for the purpose noted in the statement. A license may be granted for the period from **19.2.2022 to 18.2.2025** Both the days Inclusive.

Date: 24.02.2022

Signature of the Engineer

T. Murugesan
T. MURUGESAN B.E., M.I.E., F.I.V.,
DISTRICT INSPECTOR ENGINEER
TUTICORIN
42, NORTH COTTON ROAD,
TUTICORIN - 1
Phone : 2326441, 2331724
Cell No : 98421 21441

Registration No. : D.Dis.No. (CI) 7721 / 2000 of collector,
Thoothukudi District; under class IA category.

Address: T.Murugesan B.E., M.I.E., F.I.V.,
Dist. Panal Engineer – Class IA
42, North Cotton Road,
Tuticorin – 1
Phone : 2326441 , 2331724
Cell : 98421 21441.

[Signature]

PRINCIPAL

SAKTHI VINAYAGAR HINDU VIDYALAYA
CBSE SENIOR SECONDARY SCHOOL, TUTICORIN

[Signature]

SECRETARY
SAKTHI VINAYAGAR HINDU VIDYALAYA
TUTICORIN

STATEMENT TO ACCOMPANY THE CERTIFICATE OF
STRUCTURAL SOUNDNESS

24.02.2022

Location of the Building, door Number, street & Name of the place	Age of Building	Number of Storeys	Short Description Of Structures Steel – RCC Framed or Load bearing Masonry	Purpose for Which the Building is Certified for use	The Period For which The building Is certified For use	Number of Persons to Be Accommodated	Remarks
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)
Sakthi Vinayagar Hindu Vidyalaya School S. No- 494/4A, Door No- 23, Chidambara Nagar, Tuticorin, Tuticorin taluk & district Block II (M)	39 Years old. Second Floor age 19 Years	GF, FF & SF	Load bearing Structure RCC Roofing & Cement flooring in GF & FF, RCC and AC Sheet roofing & Cement flooring in SF.	For conducting School Classroom	19.2.2022 to 18.2.2025	1000 (One Thousand)	The building is structurally sound

FORM 'C' DECLARATION

I, T.Murugesan normally officiating at 42, North Cotton Road, Tuticorin do hereby declare that I possess the Qualification and experience specified in the table Rule II of the Madras Public Building Licensing Act. 1966 for issuing the certificate of structural soundness of the Building covered by this certificate.

Registration No : D.Dis.No. (CI) 7721 / 2000
Category : Class IA.

Address: T.Murugesan B.E.,M.I.E.,F.I.V.,
Dist. Panal Engineer – Class IA
42, North Cotton Road,
Tuticorin – 1
Phone : 2326441 , 2331724
Cell : 98421 21441.

T. Murugesan

Signature of the Engineer

T. MURUGESAN, B.E., M.I.E., F.I.V.,
DISTRICT PANEL ENGINEER
D. Dis. No. (CI) 7721 / 2000
42, NORTH COTTON ROAD,
TUTICORIN - 626 001.
Phone No : 0461-2331724, 2326441
Cell No : 98421 21441

Sakthi

D.Dis(B5) 1157/2022

Taluk Office
Tuticorin
Dated: 03.2022

**Form-D
(Revised)**

Form of Certificate of Structural Soundness Under Sub Sec.4 of the Tamil Nadu Public Building (Licensing Act 1965) Madras Act 13 of 1965) referred to in Rule 4 of the Madras Public Building Licensing Rules 1966.

License No: 171 /2022

I certify that I have inspected the building mentioned in the statement below and I have satisfied myself that the building is structurally sound to be used as a public building for the purpose mentioned in the statement. The Structural soundness of the building has been verified taking in to account the loading standard as per the latest Indian standard Institute 875. A License is granted for the period of three year from 19.02.2022 to 18.02.2025
Statement to accompany the certificate of structural soundness.


Location of the Building (Door No, Street and Name of Place)	Age of the Building	The Period of which the building is certified for use	No.of persons to be accommodated	Purpose
Sakthi vinyagar Hindu Vidyalaya School S.No - 494/4A, Door No -23, Chidambara Nagar, Tuticorin , Tuticorin Taluk & district Block II (M)	39 years old Second floor Age 19 Years	19.02.2022 to 18.02.2025	1000 (One Thousand Only)	Using as School


To,
The Correspondent,
Sakthi vinyagar Hindu Vidyalaya School
Door No -23,
Chidambara Nagar,
Tuticorin




PRINCIPAL

**SAKTHI VINAYAKAR HINDU VIDYALAYA
CBSE SENIOR SEC.SCHOOL, TUTICORIN**




Tahsildar
Thoothukudi



**SECRETARY
SAKTHI VINAYAKAR HINDU VIDYALAYA
TUTICORIN**

FORM – E

Form of report to be made to be to the competent Authority by Inspecting Authorities of officers appointed under section 28 of the Madras Building (Licensing) Act 1965 referred to in the rule 7 of the Madras Public Buildings (Licensing) Rule 1966.

Name and designation of the Inspecting Authority of officer appointed or having Jurisdiction under any other Act or Rule. : T. MURUGESAN
Chartered Engineer & Approved Valuer
Tuticorin.

Location of the building inspected : **Sakthi Vinayagar Hindu Vidyalaya**
Door No./ street No./ Name of place **School**
i.e. Municipal corporation / S.No-494/4A, Door No-23,
Municipality/ Panchayat or Chidambara Nagar, Tuticorin
Panchayat union/ Township/ Tuticorin taluk & district
cantonment

Date of Inspection : 24.02.2022

Purpose for which the building is used : **School class room**

Nature of defects noticed : Nil

Suggestion for rectifying Defects : The building should be maintained periodically

If in dangerous conditions, immediate steps recommended to be taken : Nil






T. MURUGESAN, CHARTERED ENGR.,
DISTRICT ENGINEER,
D. Dis. No. 100/2022, TU
42, NEETHI, CHIDAMBARA ROAD,
TUTICORIN-695 002.
Phone On: 0471-235270, 2326441
Cell No: 9842121494